

Tele : 25691075

Garrison Engineer (Central)
Military Engineer Services
Delhi Cantt – 10

2008/Imp Corr/ 69 /E2

04 Mar 2024

HQ Delhi Area (Q)
Delhi Cantt – 10

STRUCTURAL STABILITY OF BLDGS : APS DHAULA KUAN

1. APS Dhaula Kuan was visited by the undersigned on 04 Mar 2024. Upon visual inspection of the school bldgs., it was found that the bldgs. Are in good state and no major repairs are required. As per the preliminary inspection, bldgs appear to be safe.
2. For info pl.

Copy to :-

HQ CWE
Delhi Cantt – 10

APS Dhaula Kuan
New Delhi – 10



Subha
WAE
GE (Central)
कप्तान / Captain
सहायक दुरी अभियंता पदवी
AGE BTL (Central)
दिल्ली छावनी-90/Delhi Cantt-10